# BannerSaver

# THE SPRING-LOADED LIGHT POLE **BANNER BRACKET SYSTEM**

BannerSaver is the world's original and leading performance banner bracket. In high-wind, the patented spring-loaded bracket releases, reducing stress on and increasing the life of banners and poles. When the wind dies down, the banners return to their original position. Often imitated, never duplicated, BannerSaver is wind tunnel-tested to spill 87% of the wind and is the most specified banner bracket in the world.

## TOP PRODUCT BENEFITS

Reduces damage and light pole liabilities. Spring-loaded, wind-release 2 bracket keeps banners safe. Patented hardware is specified on six continents. Wind tunnel-tested to spill 87% of wind load.

5

6

- Ideal for festivals, streetscapes, parking lots, and more.
- In use at hundreds of cities and venues across the world.





1-800-236-0112

5100 West Brown Deer Road www.tapconet.com Brown Deer, WI 53223



U.S. COMMUNITIES

BannerSaver™



## **BANNERSAVER | SPECIFICATIONS**

Warranty	10-year
Patent Number	#5388794

## **BANNERSAVER** | STANDARD SIZES

Standard sizes are detailed below.

Product	Maximum Banner Size
Small BannerSaver	Up to 17.5 sq. ft.
Medium BannerSaver	Up to 20 sq. ft.
Large BannerSaver	Up to 23 sq. ft.
XL BannerSaver	Up to 30 sq. ft.

Heavy banding is suggested for all installs, and is required when installing Large and XL BannerSaver brackets. Standard banding works fine for most installations of Small or Medium BannerSaver brackets. With standard banding, the poles must be round, metal, and over 4" in diameter.

## **BANNERSAVER** | ACCESSORIES

#### **Each Set of BannerSaver Brackets Includes:**

- $\rightarrow$  Two-piece base casting
- ightarrow Spring tensioned assembly
- ightarrow 2 sleeved black fiberglass arms
- ightarrow 2 large safety pins
- $\rightarrow$  2 large plastic zip ties
- $\rightarrow$  Mounting instructions



1-800-236-0112 5100 West Brown Deer www.tapconet.com Brown Deer, WI 53223 5100 West Brown Deer Road









# FIBERFLEX | ECONOMY BRACKETS

Standard bracket designed for short-term or budget-conscious installations.



COMPARISON CHART	BANNERSAVER	KBW ARROW
Spills 87% of the wind	✓	
Loads less then 200 lbs. of force on poles	✓	
Loads more then 600 lbs. of force on poles		$\checkmark$
Works with banners up 30 sq. ft.	$\checkmark$	
Works with any bracket arm length	✓	
Changes banner sizes easily with minimal cost	✓	
Specified and/or Installed on six continents	$\checkmark$	
Pivots in four directions	$\checkmark$	



1-800-236-0112 5100 West Brown Deer Road www.tapconet.com Brown Deer, WI 53223







### **BANNERSAVER | MAINTENANCE**

With regular maintenance, your BannerSaver<sup>™</sup> will last for years, protecting banners and reducing light pole liabilities. We recommend the following maintenance schedule:

- Return to the install site within 2-4 weeks of the first install to tighten bands if necessary.
- Check on banding once a quarter and/or after high wind storms. It may be necessary to tighten or replace banding from time to time.
- Note: All banding of any kind, from any company, requires maintenance. Heavy banding costs more up front but will reduce maintenance costs in the long run.

# **BANNERSAVER** | WARRANTY

Britten, Inc. provides a ten-year warranty on the BannerSaver<sup>™</sup> against product design, manufacturing and its wind-spilling capabilities as outlined in the BannerSaver<sup>™</sup> Wind Tunnel Test Report and assuming proper installation methods. During this warranty period, Britten, Inc. will replace or repair the BannerSaver<sup>™</sup>. This warranty applies only to the original purchaser and is in lieu of all other warranties either expressed or implied for a period of ten years from the date of purchase. Britten, Inc. will not warrant the following: SHIPPING; customer is to bear all shipping expense to return the unit to Britten. LABOR; associated with the removal or installation. DAMAGE; caused by misuse, neglect abuse, accidents, alterations, corrosive environments and any other abnormal service conditions. This warranty specifically does not include product damage due to weather conditions rated F-O and higher (65mph) on the National Weather Service Fujita Scale.

#### Claims against the warranty must include:

- Clear pictures of installations, including proper banding; and
- National Weather Service reporting based on the day of inquiry.

BannerSaver<sup>™</sup> customers recognize that performance related products like the BannerSaver<sup>™</sup> require occasional maintenance including checking for loose banding and/or the replacement of bands. Britten encourages customers to remove light pole banners from poles when a known F-O or higher storm is expected.

#### Important notes:

- The customer is responsible for all wall mounted installations, and warranties do not apply due to the wide variation in walls.
- Domestic (United States) sales to resellers and end-users are made upon the explicit, mutual understanding that all installations will be within the United States unless previously agreed upon in writing.



<sup>®</sup> 1-800-236-0112 www.tapconet.com

5100 West Brown Deer Road Brown Deer, WI 53223





BannerSaver™

